

## **Metro Count Speed Survey Result for Hindon Lane, Tisbury (30 mph Speed Limit)**

The Results of the survey for the area of Hindon Lane, Tisbury are provided below.

The survey was carried out between 30/07/2012 and 14/08/2012. A total of 24211 vehicles were checked. The 85<sup>th</sup> percentile was 31.5mph (the 85<sup>th</sup> percentile is the speed at which 85% of the traffic is travelling at or below).

As with every other department, we have to target our limited resources to where they will be most effective and as such I would remind you that unless there are exceptional circumstances we will not accept another count request for this location or close surrounding area for another 12 months. For your information the thresholds for interventions are below;

In a 30mph speed limit the following criteria will be applied:

30 to 34.9mph 85<sup>th</sup> percentile = No Further Action (NFA)

35 to 38.9 mph 85<sup>th</sup> percentile = eligible for Community Speed Watch

39 to 42 mph 85<sup>th</sup> percentile = eligible for the Speed Indicator Device (SID) programme

Community Speed Watch does not operate in any speed limit above 40mph.

Any other results in higher speed limits will be discussed on their individual basis and merit.

Yours sincerely

Road Safety Driving  
roadsafetydriving@wiltshire.gov.uk  
01225 701970

## MetroCount Traffic Executive Speed Statistics by Hour

### SpeedStatHour-104 -- English (ENG)

#### Datasets:

**Site:** [HINDON LANE TISBURY] HINDON LANE TISBURY (40MPH)  
**Direction:** 7 - North bound A>B, South bound B>A. **Lane:** 0  
**Survey Duration:** 10:12 19 September 2012 => 10:43 27 September 2012  
**Zone:**  
**File:** HINDON LANE TISBURY27Sep2012.EC0 (Plus)  
**Identifier:** M6218D6C MC56-6 [MC55] (c)Microcom 02/03/01  
**Algorithm:** Factory default (v3.21 - 15275)  
**Data type:** Axle sensors - Paired (Class/Speed/Count)

#### Profile:

**Filter time:** 10:13 19 September 2012 => 10:43 27 September 2012  
**Included classes:** 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12  
**Speed range:** 6 - 99 mph.  
**Direction:** North, East, South, West (bound)  
**Separation:** Greater than 4.00 seconds. - (Headway)  
**Name:** Default Profile  
**Scheme:** Vehicle classification (ARX)  
**Units:** Non metric (ft, mi, ft/s, mph, lb, ton)  
**In profile:** Vehicles = 15739 / 19312 (81.50%)

## Speed Statistics by Hour

### SpeedStatHour-104

**Site:** HINDON LANE TISBURY.0.0NS  
**Description:** HINDON LANE TISBURY (40MPH)  
**Filter time:** 10:13 19 September 2012 => 10:43 27 September 2012  
**Scheme:** Vehicle classification (ARX)  
**Filter:** Cls(1 2 3 4 5 6 7 8 9 10 11 12 ) Dir(NESW) Sp(6,99) Headway(>4)

Vehicles = 15739

Posted speed limit = 37 mph, Exceeding = 9196 (58.43%), Mean Exceeding = 42.30 mph

Maximum = 85.2 mph, Minimum = 7.7 mph, Mean = 38.3 mph

85% Speed = 44.3 mph, 95% Speed = 48.8 mph, Median = 38.0 mph

12 mph Pace = 32 - 44, Number in Pace = 11349 (72.11%)

Variance = 40.68, Standard Deviation = 6.38 mph

### Hour Bins (Partial days)

Time	Bin		Min	Max	Mean	Median	85%	95%	>PSL 37 mph	
0000	71	0.5%	9.4	59.4	37.9	38.0	45.0	51.9	39	54.9%
0100	32	0.2%	26.2	50.8	39.6	40.5	44.3	45.6	22	68.8%
0200	13	0.1%	29.0	56.7	42.4	44.3	53.0	54.4	8	61.5%
0300	17	0.1%	30.5	59.8	41.3	39.4	49.0	53.9	11	64.7%
0400	17	0.1%	34.2	60.1	46.1	47.0	51.7	57.9	14	82.4%
0500	95	0.6%	29.8	85.2	44.9	43.6	53.0	59.7	82	86.3%
0600	302	1.9%	14.6	74.2	41.9	40.9	49.4	55.7	226	74.8%
0700	849	5.4%	11.2	67.1	40.0	39.8	46.3	50.3	614	72.3%
0800	1130	7.2%	10.7	62.9	38.6	38.5	44.5	48.3	723	64.0%
0900	1113	7.1%	10.6	62.7	38.1	37.8	43.6	47.6	646	58.0%
1000	1068	6.8%	9.7	64.5	37.1	37.1	42.9	47.6	547	51.2%
1100	1047	6.7%	8.3	58.6	37.5	37.4	43.4	47.4	555	53.0%
1200	1077	6.8%	7.7	63.3	37.5	37.4	43.2	46.5	583	54.1%
1300	1013	6.4%	7.7	59.5	37.8	37.1	43.8	47.6	532	52.5%
1400	1031	6.6%	8.9	57.8	37.9	37.8	43.6	47.6	577	56.0%
1500	1056	6.7%	9.9	64.9	38.0	37.6	43.6	47.9	602	57.0%
1600	1234	7.8%	10.4	58.4	38.0	37.8	43.6	48.3	708	57.4%
1700	1324	8.4%	16.9	74.3	38.4	38.0	43.6	47.4	785	59.3%
1800	1087	6.9%	11.3	63.0	38.8	38.5	44.7	49.0	686	63.1%
1900	825	5.2%	12.3	67.5	37.8	37.6	44.1	49.0	443	53.7%
2000	516	3.3%	16.7	63.8	38.4	38.0	45.2	50.8	287	55.6%
2100	381	2.4%	17.8	70.5	39.7	38.7	46.3	50.6	243	63.8%
2200	272	1.7%	16.9	74.9	39.0	38.5	46.8	52.6	163	59.9%
2300	169	1.1%	20.0	67.6	39.0	37.6	45.6	50.8	100	59.2%

## **Metro Count Speed Survey Result – The Avenue, Tisbury (30 mph Speed Limit)**

The Results of the survey for the area of The Avenue are provided below.

The survey was carried out between 17/04/2012 and 25/04/2012. A total of 8565 vehicles were checked. The 85<sup>th</sup> percentile was 32.9mph (the 85<sup>th</sup> percentile is the speed at which 85% of the traffic is travelling at or below).

As with every other department, we have to target our limited resources to where they will be most effective and as such I would remind you that unless there are exception circumstances we will not except another count request for this location or close surrounding area for another 12 months. For your information the thresholds for interventions are below;

In a 30mph speed limit the following criteria will be applied;

30 to 34.9mph 85<sup>th</sup> percentile = No Further Action (NFA)

35 to 38.9 mph 85<sup>th</sup> percentile = eligible for Community Speed Watch

39 to 42 mph 85<sup>th</sup> percentile = eligible for the Speed Indicator Device (SID) programme

Community Speed Watch does not operate in any speed limit above 40mph.

Any other results in higher speed limits will be discussed on their individual basis and merit.

Yours sincerely

Road Safety Driving  
roadsafetydriving@wiltshire.gov.uk  
01225 701970

Tuesday, 15 January 2019

**Traffic Speed Survey Result Hindon Lane, Tisbury (20mph Speed Limit)**

- North of Duck Street

The Results of the survey for the area of Hindon Lane are provided below.

The survey was carried out between 19/09/2017 and 27/09/2017. A total of 15152 vehicles were checked. The 85<sup>th</sup> percentile was 31.1mph (the 85<sup>th</sup> percentile is the speed at which 85% of the traffic is travelling at or below). The average speed was 25.5mph.

As with every other department, we have to target our limited resources to where they will be most effective and as such I would remind you that unless there are exceptional circumstances we will not accept another count request for this location or close surrounding area for another 12 months.

**Community Speed Watch does not operate in any speed limit above 40mph.**

**In a 20mph speed limit the following criteria will be applied;**

20 to 24mph 85<sup>th</sup> percentile = No Further Action (NFA)

24.1 to 38.9 mph 85<sup>th</sup> percentile = eligible for Community Speed Watch

Over 39mph 85<sup>th</sup> percentile = Subject to Police enforcement

Any other results in higher speed limits will be discussed on their individual basis and merit.

Yours sincerely

Road Safety Driving  
roadsafetydriving@wiltshire.gov.uk  
01225 701970